

DEPARTMENT OF TRANSPORTATION

DIVISION OF ENGINEERING SERVICES

Office of Structural Materials

Quality Assurance and Source Inspection



Bay Area Branch
690 Walnut Ave.St. 150
Vallejo, CA 94592-1133
(707) 649-5453
(707) 649-5493

Contract #: 04-0120F4Cty: SF/ALA Rte: 80 PM: 13.2/13.9File #: 50.15**SOURCE INSPECTION REPORT****Resident Engineer:**Pursell, Gary**Address:** 333 Burma Road**City:** Oakland, CA 94607**Report No:** SIR-000327**Date Inspected:** 16-Dec-2008**Project Name:** SAS Superstructure**OSM Arrival Time:** 700**Prime Contractor:** American Bridge/Fluor Enterprises, a JV**OSM Departure Time:** 1900**Contractor:** Zhenhua Port Machinery Company, Ltd (ZPMC), Jiangyin**Location:** Changxing Dao, Shanghai

Quality Control Contact:	William Oak (ABF) Paint Supervisor			Quality Control Present:	Yes	No	
Material transfer:	Yes	No	N/A	Sampled Items:	Yes	No	N/A
Stock Transfer:	Yes	No	N/A	OK to Cut:	Yes	No	N/A
Rebar Test Witness:	Yes	No	N/A	Delayed/Cancelled:	Yes	No	N/A
Other:	Coatings Inspection						
Bridge No:	34-0006			Component:			
Bid Item:	79			Lot No:			

Summary of Items Observed:

There was no coatings related work performed by the contractor today. A shipment of Inerzinc 22 due to be delivered today will not arrive until tomorrow.

Summary of Conversations:**Comments**

This report is for the purpose of determining conformance with the contract documents and is not for the purpose of making repair or fit for purpose recommendations. Should you require recommendations concerning repairs or remedial efforts please contact Jordan, Don, who represents the Office of Structural Materials for your project.

Inspected By:	Jordan,Don	Quality Assurance Inspector
Reviewed By:	Mertz,Robert	QA Reviewer